

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/29/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/27/2012 – 0700, 12/10/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Larry Rader		Situation Unit Leader	Chicago, IL
8. Activity Log			
Time	Major Events		
09:00	<ul style="list-style-type: none"> Arrived at C0.4 boat launch. No sheen observed in vicinity of trestle above Ceresco Dam. Bank ice observed along LDB and RDB on upstream and downstream sides of trestle. No sheen, some debris observed within Ceresco Dam containment boom. Ice observed in debris along with surface ice fragments at boom. Ceresco Dam control point, observed bathymetry survey crews operating along LDB below trestle and RDB above Dam. 		
10:30	<ul style="list-style-type: none"> Depart C0.4 boat launch, mob. to Brooks Field for Helicopter overflight. 		
11:00	<ul style="list-style-type: none"> Take off at Brooks Field. Source area, observed ice on standing water at Source Area. Talmadge Creek, observed the new line 6B work. Frac-Tank decontamination pad, observed crews around boom in decon area. Construction of winter shelter next to decon pad appears complete. Ceresco Dam control point, observed bathymetry survey crews operating along RDB below trestle. MP15.5, observed utility crews excavating in river near Burnham Street bridge. MP21.25 oxbow, no sheen or ice observed. MP27.0, observed sweeper boat operating on river at Shady Bend Campgrounds. MP 28.25 oxbow, no sheen or ice observed. Morrow Lake Delta, observed pontoon boat crew pulling boom anchors in western end of delta. Ice observed along northern shore of Morrow Lake west of Rowe Island and at western end of lake near the dam. 		
12:00	Returned to ICP.		
9. Prepared by (Name and Position)			

